

Collection


Rubacuori

Article

RU319


Description

Wall mounted waterfall.





Dimensions




P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it

f
P





Elenco parti			
ELEM.	CODICE	NUMERO DI MAGAZZINO	QTÀ
1	AC0011408	Plate 250x130x3	1
2	AQ0012261	Rubber packing double-sided tape 245x90x1	1
3	AQ0009809	Screw M4x30	4
4	CPKMH319CCX02	Preassembled waterfall spout	1
4.1	AC0011331	Spout-out 200x60x54.5	1
4.2	AQ0009818	OR 14x1.78 NBR 70 SH	1
4.3	AS0011376	Nipple G1/2" M G3/8" M H28	1
4.4	AQ0016963	Flow reduction valve 20 Lt (red) (58.6139.1)	1
4.5	AQ0009678	Seeger Ø15.5	1
4.6	AQ0012264	OR 2x130 NBR 70 SH	1
4.7	AQ0012265	Closing plate	1
4.8	AQ0012263	Screw M4x10	7
5	AQ0012266	Thickness 10x10x30 fori Ø8.5	2
6	AQ0013078	Fixing box wall	1



T. +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v.

www.weareib.it





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.


Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy -

T. +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it

