

Collection

BELMONDO


Article


BL410

Description

Three holes wall mounted shower







Ceramic headwork G1/2" ceramic headwork	Threaded fitting G1/2" female			
 Aerator	Flow Rate (+/-10%)			
	1 BAR 28 I\min	2 BAR 40 l\min	3 BAR 49.3 l\min	

Production

Main body is a single casted pieces

Material

BRASS

According to CuZn35Pb2AL-B (CB752S)

Max Lead content: 1.36%





	Parts list		
ELEM COD		QT	
1 CT00020		2	
2 AQ0010		1	
3 AQ0010	528 Ceramic headwork 90° DX H38.5 8x20	1	
4 AQ0010	617 Click connection for headworks	3	
5 AQ0010	Rubber packing Ø38x33.5x2	3	
6 CC0002	162 Octagonal bell H70	2	
7 AQ0010	153 OR 10x2 NBR 70 SH	3	
8 CC0002	160 Lever	3	
9 AQ0010	279 Diverter	1	(1)(9)
10 AS00099		1 (
11 CC0002	Octagonmal bell W26x19 H50	1	
8 7		5 10	4





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.

