

Collection

BIRKIN


Article

BR396_2

Description

Five holes deck mounted bath filler with shower kit.





 Ceramic headwork

 Aerator
 Flow Rate (+/-10%)

 M24x1
 1 BAR 2 BAR 3 BAR 13.7 l\m

 1 9.6 l\m
 24.1 l\m

Main body is a single casted pieces

Production

Material

BRASS

According to CuZn35Pb2Al-B (CB752S)

Max Lead content: 1.36%





		Parts list		
ELEM.	CODE	DESCRIPTION	QTÀ	
1		Marble cover Ø55 H32	3	
		Screw Ø7.1 M6 H9 dark gray	3	
		Screw M4x10	3	
		OR 26.7x1.78 NBR 70 SH	6	
		Handle Ø29.9 H19	3	
		Base Ø80 H16 M24x1	2	
		OR 65.1x3.53 NBR 70 SH	4	
		Rubber packing 45x35x2	5	
	AS0010697	Washer Ø48 x Ø26.5 x3	5	
		Ring nut W26x19	3	
		screw M5x16	10	
		Ceramic headwork 90° left	1	
		Washbasin upright W26x19	2	
		Inox Hose G1/2" 370mms	2	$\overline{2}$
	CC0001003		1	
		Plane rubber Ø44 Ø36 H3	1	
		Neostrahl M24X1 (01.9664.1)	1	(3)
		OR 17.16x1.78 NBR 70 SH	1	
		Threaded stem G3/4" G1/2" L70	1	4
20	AS0012647	Ring nut G3/4"	2	
	AQ0012033		1	(5)
		Ceramic headwork 90° right	1	
		Base Ø80 H18 26x19	1	
24	AQ0012031	Extension for diverter 26X19"	1	(23)
		Diverter 2 inlet / 2 outlet with stop (2950)	1	9000
26	AQ0009555	Second Terminal M15x1.5	1	7
27	AN0012829	Stem G3/4" H58	1	
28	AC0012828	Base Ø80 H14 G3/4"	1	
29	AQ0013557	Onair hand shower	1	
()	3			17 10 11 25
(7	16		
(9	8)	
			1	
(11)	9 20 11 14		21 (15)





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.


Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.





□ f P