

Collection

REFLEX

Article

RX321


Description

Short wall mounted spout





s 137 [5.39 in] 128 [5.04 in]



Cartridge Threaded fitting G1/2" male Aerator M16.5x1 Production Threaded fitting G1/2" male Flow Rate (+/-10%) 1 BAR
2 BAR
3 BAR
3.9 l\min Material

## Main body is a single hot stamped pieces

BRASS According to CuZn42 (CW510L) Max Lead content: 0.2%





**P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it





Parts list			
ELEM	CODE	DESCRIPTION	QT
1	CPX321CC	Preassembled spout Ø18	1
	XN_19		
1.1	AC0011994	Spout-out M18x1 M16.5x1 Ø18 L144	1
1.2	AQ0014147	Perlator PCA cachè laminar 1 GPM	1
		(44.3358.010)	
1.3	AS0016647	Fitting G1/2M M18X1F L18	1
2	AC0016653	Rosotte Ø60 H5.5 con OR	1
3	AQ0006997	OR 18x2 NBR 70 SH	1







**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - T. +39 030 802101 F. +39 030 803097 info@ibrubinetterie.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it



## WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

## The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.


Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

## Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy -

T. +39 030 802101 F. +39 030 803097 info@ibrubinetterie.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it

