



Release notes SpaceLogic DFU tool DFU_B_00_06_00

July 2021


Content

- FW package details
- Release notes

DFU tool details

DFU_B_00_06_00

- SpaceLogic KNX devices diagnostic via KNX



More details about diagnostic via KNX available in helpfile

FW package details

SpaceLogic_KNX_DFU 00_30.zip

- SpaceLogic_KNX_DFU 00_30.cms
- SpaceLogic Universal Switch actuator
 - OM08RLYR_B_12_08_00.bin => updated
 - OE08RLYR_B_12_08_01.bin => updated
- SpaceLogic Universal Dimming actuator
 - OM02DIMR_B_03_09_00.bin => updated
 - OE02DIMR_B_03_09_00.bin => updated
- SpaceLogic KNX DALI Gateway (HW version A)
 - SEDCPro_V1.0.5_partial.bin => no change
 - SEDCPro_V1.0.5_unconditional.bin => no change

Release notes – BugFixes

SpaceLogic Universal Switch actuator

- Blind / shutter functionality: Slat Feedback is not sent in specific situation
- Blind / shutter functionality: Device not accept the command during driving up
- Bootloader version separate reading for diagnostic information

Release notes – BugFixes

SpaceLogic Universal Dimming actuator

- Fast OFF line / ON Line of Dimmer core create malfunction caused by impossibility to detect load
- Bootloader version separate reading for diagnostic information
- HW key identification and detection for diagnostic information
- + bugs linked to Switch actuator (dimmer include switch actuator FW too)

Life Is On

Schneider
Electric

