

Collection

# Handshower

Article


# **SH013**

Description

# Round shower three jets CLEAN PLUS

Box Dimensions			Weight		
280x130	κ70 mm		0.7 kg		
Finishes					
● CC CHROME	OPL	OSS BRUSHED NICKEL	ON NATURAL BRASS	OBO MATT WHITE	O NP MATT BLACK
O CF BLACK CHROME	OCS BRUSHED BLACK CHROME	OII PALE GOLD	OIS BRUSHED PALE GOLD	ORS ROSE GOLD	O SR BRUSHED ROSE GOLD
OOO	OOS BRUSHED GOLD	ORR ANTIQUE COPPER	OBB ANTIQUE BRONZE		





-	G1/2" M
Aerator	Flow Rate (+/-10%)
-	1 BAR 2 BAR 3 BAR - I\m - I\m - I\m

Main body is a single hot stamped pieces

\_

Material



Production



Parts list							
ITEMS	CODE	DESCRIPTION	QTÀ				
1	AQ0015213	Hand shower clean three jets 12x12	1				







#### WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

### The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.


Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

### Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.





**□** f P