

Collection

HERMES

Article

HR397

Description

Four hole deck-mounted bath filler with overflow outlet

connection

Box Dimensions 360 x 220 x 150 mm Weight

5 kg

Finishes

CC CHROME

OCF

000

 \bigcirc BG GLOSSY WHITE ONG GLOSSY BLACK

BB

OSS BRUSHED NICKEL OCS BRUSHED BLACK CHROME

ANTIQUE BRONZE

RR ANTIQUE COPPER

ORS ROSE GOLD

 \bigcirc BO

ON NATURAL BRASS

ONP


OIS BRUSHED PALE GOLD OHH PVD CHOCOLATE











Headworks

IB G1/2" Ceramics Headworks

Treaded fitting

Treaded fitting G1/2" male

Aerator

Flow Rate (+/-10%)

1 BAR 19.7 I\min 2 BAR 27.5 I\min 3 BAR 33.1 I\min

Production

Material

BRASS

According to CuZn35Pb2Al-B (CB752S)

Max Lead content:1.36%

IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy -

T. +39 030 802101 F. +39 030 803097 info@ibrubinetterie.it P.IVA 01785230986 capitale sociale €420.000,00 i.v.


WWW.IBRUBINETTI.IT















WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.

