

Collection

MILANO TORINO

MT200

Description

Monohole washbasin mixer

Box Dimensions Weight 340x180x70 mm 1.6 kg

Finishes

● CC CHROME



BRUSHED NICKEL







CF BLACK CHROME

CS BRUSHED BLACK CHROME

IS BRUSHED PALE GOLD

RS ROSE GOLD

SR BRUSHED ROSE GOLD

OO GOLD


OS BRUSHED GOLD

ORR ANTIQUE COPPER

OBB ANTIQUE BRONZE







Cartridge

Ø25 ceramic cartridge

Threaded fitting

Inox hoses G3\8" female 400 mms long

Aerator

Flow Rate (+/-10%)

M16.5X1

1 BAR 6.5 l\m 2 BAR 9 I\m

3 BAR 11 I\m

Production

Main body is a single casted pieces

Material

BRASS

According to CuZn42 (CW510L) Max Lead content: 0.2%

IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - T. +39 030 802101 F. +39 030 803097 info@weareib.it

P.IVA 01785230986 capitale sociale €420.000,00 i.v.

www.weareib.it







Parts list

DESCRIPTION

QT

1

1

1

1

1

1

1

1

1

1

1

1

1

1


1

2

1

1

1







WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.


Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.





□ f P