



Models/Modelos/Modèles  
501LF-WF & 520LF-WFMPU  
Series/Series/Seria



RP26533 Metal Pop-Up Assembly Less Lift Rod  
Ensamble de Metal del Desagüe Automático Menos la Barra de Metal  
Renvoi Mécanique en Métal Sans la Tige de Manoeuvre

\*RP51505 adapter is only compatible with aerators produced before 6/13/2011.



\*RP51505 adapter is only compatible with aerators produced before 6/13/2011.

\*RP51505 adapter is only compatible with aerators produced before 6/13/2011.

\*\*If you are unsure of the manufacture date, please order both aerators in the flow rate you desire.

\*\*Si no está seguro de la fecha de fabricación, por favor, ordene ambos aireadores para el flujo deseado.

\*\*Si vous n'êtes pas certain de la date de fabrication, veuillez commander les aérateurs de chacun des modèles qui ont les caractéristiques de débit que vous désirez.

RP60729 0.5 GPM	RP60983 1.5 GPM	RP72676 0.35 GPM	RP71111 0.5 GPM	RP54977 1.5 GPM
Aerators for faucets made before 6/13/2011		Aerators for faucets made after 6/13/2011		
Aereadores para llaves de agua/grifos fabricados antes de 6/13/2011		Aereadores para llaves de agua/grifos fabricados después de 6/13/2011		
Aérateurs pour les robinets fabriqués avant le 13/06/2011		Aérateurs pour les robinets fabriqués après le 13/06/2011		
 O-ring Seal Anillos "O" Joints Torique		 Gasket Seal Empaque Joint		